


East End of Runway at Brandis Airfield



Legend:

- 1 Extension of runway, constructed by Soviets.
It is in good condition.
- 2 Drainage ditches, about 35 cm wide, partially covered with flat cement stones.
- 3 Cement recesses, each 0.8 x 2.5 meters and covered with three wooden lids.
- 4 Old runway with asphalt cover, constructed in 1945, repaired with cement, in good condition.
- 5 Asphalt taxiway, in good condition.
- 6 Small curve.